

# RETAINING RINGS

Cross Reference Chart



| Anderton | Industrial | Waldes/<br>Truarc | Military<br>Standard | Spaenaur |
|----------|------------|-------------------|----------------------|----------|
| N1500    | 1000       | 5133              | MS16633              | R1000    |
| N1501    | 1001       | 5131              | MS16634              | R1001    |
| N1540    | 1200       | 5144              | MS3215               | R1200    |
| N1800    | 2000       | 5103              | MS16632              | R2000    |
| N1300    | 3000       | 5000              | MS16625              | R3000    |
| N1400    | 3100       | 5100              | MS16624              | R3100    |
| N1401    | 3103       | 5101              | MS16628              | R3101    |
| N1308    | 4000       | 5008              | MS16627              | R4000    |
| N1408    | 4100       | 5108              | MS16626              | R4100    |
| N1405    | 6100       | 5105              | --                   | R6100    |
| N1465    | --         | 5115              | --                   | 5115     |
| N1440    | 7100       | 5555              | MS90707              | 5555     |